



Nistar – Wedge Meter

Model 1000



Accuracy: $\pm 2\%$ uncalibrated, $\pm 0.50\%$ calibrated w/ Tx

Repeatability: $\pm 0.1\%$ of rate

Process temperature: Up to 1100 °F

Pressure Rating: Up to 1500psi

Minimum Reynolds Number: 500

Turn Down Ratio (TDR): Typical 10 to 1

Maximum Viscosity: Up to 5000 cP
